
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: <u>5/27/2009</u>
Test to be performed:  Smoke Dyed Water X Dry ✓ Damp ☐ Wet ☐		Supervisor: <u>JAW</u>
Manhole_ID: S03O015MH	Test ID: <u>D1032-002011</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S03O015MH
0			Water Level	
0			Dye Test Not Visible	